


Nozzle REPAIR DN 150



bottom nozzle

The simple mounting !

Repair sleeve for glass lined DN 150 central bottom outlet nozzle

Is an enameled bottom outlet nozzle size DN 150 damaged on the inside neck or flange face, it can be repaired by the EC repair sleeve. The sleeve is made of steel and covered with solid PTFE. The mounting is simple, insert the sleeve from inside and screw it up from outside - **no drilling and welding work** is necessary. The new bottom outlet has the size DN 100.

Optional we offer the sleeve in hastelloy or tantalum.

.. no drilling ..
.. no welding ..



®

EMAIL-COVER

EMAIL-COVER R. Scholz GmbH · Martin-Luther Str. 39 · 53919 Weilerswist · Germany
Telefon +49 2254 3534 262 · Fax +49 2254 3534 251
E-Mail: verkauf@email-cover.de
www.email-cover.eu